

CERTIFICATE OF COMPLIANCE

Certificate Number 20180403-SA33645
Report Reference SA33645-20120316
Issue Date 2018-APRIL-03

Issued to: GD MIDEA AIR-CONDITIONING EQUIPMENT CO., LTD.
LINGANG RD
BEIJIAO
SHUNDE
FOSHAN
GUANGDONG 528311 CHINA

This is to certify that representative samples of AIR CONDITIONERS, PACKAGED TERMINAL
“See the Models in Addendum Page”

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 484 and CAN/CSA C22.2 No. 117-1970 Standard for Room Air Conditioners.

Additional Information: See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>




CERTIFICATE OF COMPLIANCE

Certificate Number 20180403-SA33645
Report Reference SA33645-20120316
Issue Date 2018-APRIL-03

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

USL, CNL – Packaged Terminal Air Conditioner, Models US1-KCD21P/N1Z-PB(K9)-[J], MWP-07EEN1-MK9, 600495, US1-KCD35P/N1Z-PB(J7)-[J], MWP-12EEN1-MJ7, 600496, KTHM012-E3C2, US1-KCD45P/N1Z-PB(I5)-[J], MWP-15EEN1-MI5, 600497, KTHM015-E5C2, US1-KCD26P/N1Z-PB(K3)-[J], MWP-09EEN1-MK3, KTHM009-E3C2, 4130060, 4130070, 4130080, 1028085, 1028283, 1028284, MP-07EMA4-2, MP-07EMB4-2, MP-09EMB4-2, MP-12EMB4-2, MP-12EMC4-2, MP-15EMB4-2, MP-15EMC4-2, 1PTC07A-3.5, 1PTC09A-3.5, 1PTC15A-5.0, 1PTC15A-3.5, 1PTC12A-5.0, 1PTC12A-3.5, MWP-12CEN1-MJ7, MWP-15CEN1-MI5, US1-KCD45P/N1Z-DPB(I5), MWDUP-15EEN1-MI5, US1-KCD26P/N1Z-DPB(K3), MWDUP-09EEN1-MK3, US1-KCD21P/N1Z-DPB(K9), MWDUP-07EEN1-MK9, US1-KCD35P/N1Z-DPB(J7), MWDUP-12EEN1-MJ7, 2477814, 2477815, 2477816, 292462, 292465, 292466, KTHN009E3C211-B, KTHN015E5C210-B, KTHN012E3C211-BC, KTHN009E3C211-BC, KTHN015E5C210-BC, PTAC1642-07C-2, PTAC1642-09C-3, PTAC1642-12C-3, PTAC1642-15C-3, PTAC1642-07C-3, PTAC1642-09C-5, PTAC1642-12C-5, PTAC1642-15C-5, EGN-15-42B, 0-C9736, 0-C9737, 0-C9738, 0-C9739, PTAC164209CED3A, PTAC164212CED3A, PTAC164215CED3A, 2498547, 2498548, 2498549, MP07EMB62, MP09EMC62, MP12EMC62, MP15EMC62, 2498546, CH-PT12HS2, CH-PT15HS2, 4130061, 4130071, 4130081, PTAC07325, PTAC09335, PTAC12335, PTAC15335, EPTA012C10B, EPTA015C10B, PTAC164215CED5A, PTAC164212CED5A, MP09EMB52, MP12EMB52, MP15EMB52, MP07EMA52, PTAC0012MD, CH-PT09HSGF, CH-PT12HSGF, CH-PT15HSGF, 89AC09CD35, 89AC12CD35, 89AC15CD35, 0-G1249, MP15EMB82, MP07EMB82, MP12EMB82, MP15EMC82, MP12EMC82, MP09EMC82, MP09EMB82

USL, CNL – Packaged Terminal Heat Pump, Models US1-KCR26P/DN1Z-PB(K3)-[J], MWP-09AEN1-MK3, 600499, KTHM009-E3H2, US1-KCR35P/DN1Z-PB(J5)-[J], MWP-12AEN1-MJ5, 600500, KTHM012-E3H2, US1-KCR45P/DN1Z-PB(I6)-[J], MWP-15AEN1-MI6, 600498, KTHM015-E5H2, US1-KCR21P/DN1Z-PB(K9)-[J], MWP-07AEN1-MK9, 4130160, 4130170, 4130180, 1028285, 1028286, 1028287, MP-07HMA4-2, MP-07HMB4-2, MP-09HMB4-2, MP-12HMB4-2, MP-12HMC4-2, MP-15HMB4-2, MP-15HMC4-2, PTHP07K230V20A-M3, PTHP07K230V15A-M3, PTHP09K230V20A-M3, PTHP12K230V20A-M3, PTHP12K230V30A-M3, PTHP15K230V20A-M3, PTHP15K230V30A-M3, US1-KCR45P/DN1Z-DPB(I6), MWDUP-15AEN1-MI6, US1-KCR26P/DN1Z-DPB(K3), MWDUP-09AEN1-MK3, US1-KCR21P/DN1Z-DPB(K9), MWDUP-07AEN1-MK9, US1-KCR35P/DN1Z-DPB(J5),



Bruce Mahrenholz, Director North American Certification Program

UL LLC


Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20180403-SA33645
Report Reference SA33645-20120316
Issue Date 2018-APRIL-03

MWDUP-12AEN1-MJ5, LVPT12KHD, 2477817, 2477818, 2477819, 292463, 292464, 292467, KTHN009E3H211-B, KTHN012E3H211-B, KTHN015E5H210-B, KTHN012E3H211-BC, KTHN009E3H211-BC, KTHN015E5H210-BC, PTAC1642-07HP-2, PTAC1642-09HP-3, PTAC1642-12HP-3, PTAC1642-15HP-3, PTAC1642-07HP-3, PTAC1642-09HP-5, PTAC1642-12HP-5, PTAC1642-15HP-5, 0-C9740, 0-C9741, 0-C9742, 0-C9743, 1PTH07A-3.5, 1PTH09A-3.5, 1PTH12A-3.5, 1PTH15A-3.5, 1PTH12A-5.0, 1PTH15A-5.0, PTAC164209HPD3A, PTAC164212HPD3A, PTAC164215HPD3A, 2498551, 2498552, 2498553, MP07HMB62, MP09HMC62, MP12HMC62, MP15HMC62, 2498550, CH-PT12HP1, CH-PT15HP1, 4130161, 4130171, 4130181, PTHP07325, PTHP09335, PTHP12335, PTHP15335, EPTA012H10B, EPTA015H10B, PTAC164215HPD5A, PTAC164212HPD5A, MP09HMB52, MP12HMB52, MP07HMA52, MP15HMB52, CH-PT09HPGF, EKTH09G135B, IPH12K20B, IPH09K20B, IPH15K20B, CH-PT12HPGF, CH-PT15HPGF, 89HP09CD35, 89HP12CD35, 89HP15CD35, 0-G1250, MP12HMC82, MP07HMB82, MP12HMB82, MP15HMB82, MP15HMC82, MP09HMB82.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

